## STATE OF UTAH **DEPARTMENT OF NATURAL RESOURCES** DIVISION OF OIL, GAS AND MINING

1594 West North Temple - Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291

Fax: (801) 359-3940

## ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	General Information					
	i.	Report Time Period: From (mo./yr.) 1/2002 To (mo./yr.) 12/2002				
	2.	DOGM File Number (Mine No): S / 035/017				
	3,	Mine Name: Little Cottonwood - Granite Extraction				
	4,	Mineral(s) Mined (or permitted to mine): Surface Granite Boulders				
i .	<b>5</b> .	Type of mine				
1	<b>6</b> .	Legal Description (Location of Lands Affected):				
		NW 1/4, SW 1/4, 1/4, Section 8, Township T35, Range R2E				
		1/4,1/4,1/4, Section, Township, Range				
		1/4,1/4,1/4, Section, Township, Range				
7.	Name of Operator or Company: Corporation of Presiding Bishop					
	8. Permanent Street Address: 15 East South Temple St. JSMB 8					
		City, State, Zip: Salt Lake City, Utah 841150-6330				
		Phone: 801-240-6448 Fax: 801-240-1335				
	9. Company Representative (or designated operator):					
		Name: Kerry B. Nielsen, AIA				
		Title: Project Architect				
		Business Address: 15 East South Temple Street				
		City, State, Zip: Salt Lake City, Utah 84150-6330				
		Phone: 801-240-6448 Fax: 801-240-1335				
		Please check if any of the above information has changed since previous year.				
11,	Mining and Reciamation					
	1.	Was there any mine related activity during the past year? Yes □ No 💆				
1	2.	If no - what was the last year of activity? 1999				
,	3.	If yes - how much one or mineral was mined? NA.				

RECEIVED

JAN 3 1 2003

	4.	additional surface disturbances that occurred during the past year.  Mineral extraction work ended December 1999		
		The site has been reclaimed by regrading	rock, stabilization and revegitation.	
		Canyon activity (climbers and hikers) have	e made ongoing disturbances on the site.	
	5.	How much additional acreage was distu	rbcd during the past year? 0	
	6.	How much acreage was reclaimed during	g the past year? 0	
	7.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  See #4		
· I I	8, 9,	What is the total disturbed acreage of entire project at years end? 0 - under our control  Briefly summarize any mining and/or reclamation plans for the upcoming year.  None		
<u>NOT</u>	<b>E</b> :	Section III., "Additional Information" ap		
III. <u>A</u> e	lditiona	l Information - R647-4-121.2 and .3		
	1. The operator shall include an updated map depicting surface disturbant performed during the year, prepared in accordance with Rule R647-4-10:			
	2.	The operator shall keep and maintain timely and shall make these records available to the	y records relating to his performance under the Act, e Division upon request.	
IV. <u>S</u>	gnatur	re Requirement		
	T her	eby certify that the foregoing is true	and correct.	
		Name (Typed or Print):	Kerry B. Nielsen, AlA	
		Title of Operator:	Project Architect	
		Signature of Operator:		
		Date:	1-30-2003	
ib				

RECEIVED

JAN 3 1 2003